

Reference	Date/Time	Location	Runway	F/W Movements	Total Movements	Complaint	Action
FW1/2026	08/04/26 1644 and 1649hrs	RH1 5HL	25R	135	163	Fixed-wing aircraft cutting the corner in the circuit and flying over residential area.	Complainant resides within the ATZ and adjacent to the crosswind leg. Aircraft identified as a P28A operated by Redhill Aviation. Email sent to operator reminding them of the correct circuit pattern. Email sent to complainant.
FW2/2026	09/04/26 1535hrs	RH1 5HL	25R	109	124	Fixed-wing aircraft cutting the corner in the circuit and flying over residential area.	Complainant resides within the ATZ and adjacent to the crosswind leg. Aircraft identified as a P28A operated by Redhill Aviation. Email sent to operator reminding them of the correct circuit pattern. Email sent to complainant.
FW3/2026	23/04/26 1604hrs	RH1 5PD	07L	147	165	Fixed-wing aircraft flying over residential property.	Complainant resides within the ATZ adjacent to the climb-out and crosswind of Rwy07. Aircraft are required to fly south and east of this location. The aircraft was identified as a C152 operated by Redhill Aviation. Email sent to the operator. Complainant updated via email.
FW4/2026	27/04/26 1026 and 1030hrs	RH1 5PD	07L	95	144	Fixed-wing aircraft flying over residential property.	Complainant resides within the ATZ adjacent to the climb-out and crosswind of Rwy07. Aircraft are required to fly south and east of this

							location. The aircraft was identified as a C152 operated by Redhill Aviation. Email sent to the operator. Complainant updated via email.
FW5/2026	27/04/26 1350hrs	RH1 5PD	07L	95	144	Fixed-wing aircraft flying over residential property.	Complainant resides within the ATZ adjacent to the climb-out and crosswind of Rwy07. Aircraft are required to fly south and east of this location. The aircraft was identified as a C152 operated by Redhill Aviation. Email sent to the operator. Complainant updated via email and phone call.
FW6/2026	30/04/26 1755hrs	RH1 5PD	07L	170	206	Fixed-wing aircraft flew over residential property.	Complainant resides within the ATZ adjacent to the climb-out and crosswind of Rwy07. Aircraft are required to fly south and east of this location. The aircraft was identified as a P28A operated by Redhill Aviation. Email sent to the operator with a request for how they intend to reduce these breaches of the published circuit pattern. Complainant updated via email