

Reference	Date	Location	Helistrip	Heli Movements	Total Movements	Complaint	Action
H1/21	17/01/21 1010hrs	RH1 5PL Within ATZ and heli circuit area	H26	43	61	This complaint relates to helicopters flying within the helicopter circuit area for H26. At the time of the complaint there was one Cabri G2 operating in the circuit.	Helicopters fly various circuit patterns with the ATZ depending on the exercise or their destination. Pilots are requested to minimise repeated overflying of particular locations. Helicopter flying within the circuit area. No action.