



Fixed-wing Flying Complaints – February 2022

Reference	Date/Time	Location	Runway	F/W Movements	Total Movements	Complaint	Action
-----------	-----------	----------	--------	------------------	--------------------	-----------	--------

Nil

Reference	Date	Location	Helistrip	Heli Movements	Total Movements	Complaint	Action
H22/01	02/02/2022 1120hrs	RH1 5PF within ATZ	H26	108	259	Helicopter overflying property located within helicopter circuit area.	This complaint relates to a solo helicopter student flying circuits to/from H26. The complainant resides within the ATZ and within the helicopter circuit pattern for H26. The location is adjacent to the downwind/base leg. helicopters should fly to the south and east of this location however pilots will overfly this location to avoid setting of CAIT and infringing the Gatwick CTR. Instructor has been rebriefed.